

ACIP RESPONSE CODES

Response Code	Rationale	Assigned		Sent to TYCOM	ACIP Process	Actions beyond ACIP
		Auto (NSLC)	ISEA			
01 -Item found on AEL	Requested NIIN is found on an AEL. The ship/facility may or may not be a user	X	X	X	NSLC will identify that the NIIN is located on an AEL instead of the APL and to identify if the ship/facility has the AEL as part of the configuration. If NSLC cannot identify the NIIN to an AEL, then ACIP will be forwarded to the ISEA for review and work.	Determine if ship/facility is properly listed as user of AEL. If not, initiate action w/ CDM to have ship/facility registered as user. Ensure proper column on AEL is utilized.
02 -Item found on lower APL	Requested NIIN is found on an accessory APL of cited APL. The ship/facility may or may not be a user.	X	X	X	NSLC will perform an upfront screening process to match the NIIN to the ships' configuration and pick the APL w/ the same EIC. If NSLC cannot match the NIIN to ship's configuration, the ACIP will be forwarded to the ISEA for review and work. Identify the APL the NIIN is found on.	Determine if ship/facility is a user of APL. If not, submit necessary information to the CDM to have the APL added. The CMD will research and correspond w/ ISEA to ensure the configuration is properly updated.
03 -Item found on Ship's 89000 APL	Requested NIIN is found on ship's/facility's 89000 APL.	X	X	X	NSLC will perform an upfront screening process to match the NIIN to the ship's configuration and pick the APL with the same EIC. If NSLC cannot match the NIIN to the ship's configuration, the ACIP will be forwarded to the ISEA for review and work.	No additional action required.
04 -Item found on higher/parent APL	Requested NIIN is found on higher/parent APL of cited APL. The ship/facility may or may not be a user.	X	X	X	NSLC will perform an upfront screening process to match the NIIN to the ship's configuration and pick the APL with the same EIC. If NSLC cannot match the NIIN to the ship's configuration, the ACIP will be forwarded to the ISEA for review and work. Identify the APL the NIIN is found on.	Determine if ship/facility is a registered user of APL. If it is, no further action is required. If it isn't, submit necessary information to the CDM to have APL added. The CDM will research and correspond w/ the ISEA to ensure the configuration is properly updated.
05 -Item found on APL w/ different PN/NIIN	Requested NIIN may already be found on APL w/ different part number.		X		ACIPs are forwarded to the ISEA for review and work.	Determine if part number cross-reference data is accurate. If not, request NAVICP make necessary changes.
06 -Item Added	Requested NIIN will be added by ISEA to the cited APL or another APL.		X		ACIPs are forwarded to the ISEA for review and work. Note: The ISEAs are responsible to inform NAVICP-MECH to add the NIIN to the APL. The preferred process to inform NAVICP-MECH is through the ICAPS program.	No additional action required.

ACIP RESPONSE CODES

Response Code	Rationale	Assigned		Sent to TYCOM	ACIP Process	Actions beyond ACIP
		Auto (NSLC)	ISEA			
07 -Item terminated	Requested NIIN is terminated w/o a replacement NIIN.		X		ACIPs are forwarded to the ISEA for review and work. When the ISEA selects this response code, a comments box will automatically be displayed. It will be mandatory for them to comment on their justification for selecting the response code.	ISEA needs to determine how fleet shall continue to maintain equipment. Take proper action to initiate support.
08 -Related APL	NIIN is listed on another APL, same system APL, superceded APL, or has its own APL.	X	X	X	NSLC will perform an upfront screening process to match the NIIN to the ship's configuration and pick the APL with the same EIC. If NSLC cannot match the NIIN to the ship's configuration, the ACIP will be forwarded to the ISEA for review and work. List APL the NIIN is found on. The ship/facility is a user of cited APL.	No additional action required.
09 -Not in TM, on drawing, or as per manufacturer	Equip Specialist has reviewed TM and/or technical drawing, or has contacted the OEM for applicability of parts, and cannot relate the NIIN/part number to the equip.'s TM.		X	X	ACIPs are forwarded to the ISEA for review and work.	If part number/NIIN is confirmed to be part of the equipment, ISEA shall take action to have part added to APL and supporting logistic documentation (TM, drawings, etc.)
10 -Item not maintenance significant or consumable	Consumables will not be added to an APL.	X	X	X	The FSC list maintained for CSM program will be used to screen out consumables.	No additional action required.
11 -NIIN Invalid	NIIN is not found in the WSF, in FEDLOG, or in DLSC databases.	X	X	X	If NIIN is invalid, then the ACIP will be sent to the TYCOM for review and work. TYCOM will provide response code and comments.	No additional action required.
12 -Item found on APL is not part of the	NIIN is listed on another APL, same system APL, superceded APL, or has own APL, but the ship/facility is		X	X	List APL number , and note that the ship/facility is not a registered user of cited APL.	ISEA needs to take appropriate action to have APL added to ships configuration. Must coordinate with CDM to have CDMD-OA updated. The TYCOM will take action to

ACIP RESPONSE CODES

Response Code	Rationale	Assigned		Sent to TYCOM	ACIP Process	Action beyond ACIP
		Auto (NSLC)	ISEA			
15 -Item on AEL with different P/N or NIIN	Requested NIIN or P/N has been superceded/replaced, and the replacement NIIN is listed on an AEL. The ship/facility is a user.	X	X		List the AEL and replacement NIIN.	Ensure proper allowance is identified in the ship's column of the AEL for this NIIN. If not have, take appropriate action to have NAVICP change quantity identified in column of AEL.
17 -NIIN already found on APL	Due to small time lag when ACIP data is created and is forwarded to the ISEA, occasionally the requested NIIN will be found on the cited APL.		X		NSLC will automatically check if the NIIN is found on the Ship's APL, and then include it in the NAVICP Allowance Process.	No additional action required.
18 -Replacem ent NIIN added to APL	The requested NIIN was cancelled and replaced by another NIIN. The ISEA will add the replacement NIIN to the APL.		X		These ACIPs are forwarded to the ISEA for review and work. When this response code is selected, it is the ISEA's responsibility to inform NAVICP-MECH to add the NIIN to the APL. The preferred process in inform NAVICP-MECH is through the ICAPS Program.	No additional action required.
20 -Reserved for system use	ISEA does not have cognizance for the cited APL. Transfer APL ownership to another ISEA.		X		These ACIPs are forwarded to the ISEA for review and work.	Ensure correct ISEA has been identified.
21 -Item beyond ships' maintenance capability, as per ISEA	SM&R codes indicates the item beyond ship's maintenance capability.	X	X	X	NSLC will establish the functionality and place in the appropriate TYCOM file. TYCOM will process these ACIPs and provide comments/ response code.	No additional action required.
22 -Item found on other APL	Requested NIIN is found on a lower, higher, or related APL. The ship/facility may or may not be a user.		X		NSLC will perform an upfront screening process to match the NIIN to the ship's configuration and pick the APL w/ the same EIC. TYCOM will process these ACIPs and provide comments/ response code. TYCOM will check the appropriate box to identify if NIIN found on lower, higher, or related APL.	No additional action required.